



## Information markings needles, nozzles and air caps

To distinguishing the different sizes needles, nozzles and air caps are marked as follows.

### Harder & Steenbeck

needle	size	marking
	0,15	_____
	0,2	=====
	0,4	=====
	0,6	=====
	0,8	no
	1,0	no
	1,2	no

Colani needles, nozzles and air caps have no markings.

nozzle	size	marking
	0,15	_____
	0,2	=====
	0,4	=====
	0,6	=====
	0,8	no
	1,0	no
	1,2	no

air cap	size	marking
	0,15	_____
	0,2	=====
	0,4	=====
	0,6	=====
	0,8	no
	1,0	no
	1,2	no

### Hansa

needle	size	marking
	0,2	_____
	0,3	=====
	0,4	=====

nozzle	size	marking
	0,2	_____
	0,3	=====
	0,4	=====

air cap	size	marking
	0,2	_____
	0,3	=====
	0,4	=====